



- NEW FLOORING
- NEW BASE
- NEW FLOORING
- NEW BASE
- NEW SKYLIGHT
- NEW PAINT (CEILING)
- NEW FLOORING
- NEW BASE
- NEW PAINT
- NEW CABINET
- NEW SINK
- NEW TOILET COMPARTMENT
- NEW PAINT
- NEW SHEET VINYL
- NEW PAINT
- RENOVATE UNUSED INNER LOCKER ROOM TO FLEX SPACE
- NEW ACOUSTIC TILE CEILING (PARTIAL)
- NEW ACOUSTIC WALL PANELS
- REPLACE ROTTED WOOD SIDING ON COVERED PLAY AREA
- NEW ADDITION TO COVERED PLAY AREA
- NEW DOOR AND SIDELIGHT
- NEW ROLLING BOOK CARTS
- NEW FLOORING
- NEW BASE
- ADD VENTILATION
- NEW CARD READER

TYPICAL IMPROVEMENTS

1. UPGRADE AND REPLACE LIGHTING THROUGHOUT
2. REPLACE 1982 INTERCOM AND CLOCK SYSTEM THROUGHOUT
3. REPLACE CHALK BOARDS WITH MARKER BOARDS

SITE IMPROVEMENTS

1. RECONFIGURE PARKING LOT FOR IMPROVED PARENT DROP-OFF
2. RENOVATE UPPER PLAYGROUND AND ADD DRAINAGE
3. CONSTRUCT STAIRWAY TO LOWER PLAY FIELD
4. ADD FENCE BETWEEN LOWER PLAY FIELD AND HILL ROAD