

NORTH CLACKAMAS SCHOOL DISTRICT

WHITCOMB ELEMENTARY SCHOOL REMODEL

GENERAL RENOVATION

1. RENOVATE 1958 BUILDING HEATING SYSTEM AND COILS
2. UPGRADE AND REPLACE LIGHTING THROUGHOUT
3. REPLACE INTERCOM AND CLOCK SYSTEM
4. FLAMEPROOF STAGE CURTAINS
5. INSTALL DRAINAGE ALONG EAST SIDE COURTYARDS
6. OVERLAY PAVE EAST DRIVEWAY AND FIRE LANE

